







Bornes à vis



RÉFÉRENCE	SECTION	L / H	INTENSITÉ	V / A	EMBALLAGE
41113	2,5 mm ²	5,2 / 42,5	20 A	590V / 24A	100
41114	4 mm ²	6,5 / 42,5	32 A	800V / 32 A	100
41115	6 mm ²	8,2 / 42,5	40 A	800V / 41A	100
41116	10 mm ²	10,2 / 42,5	50A	800V / 57A	50
41117	16 mm ²	12,2 / 42,5	63 A	800V / 76 A	50
41118	35 mm ²	15,2 / 50	100 A	1 000 V / 125 A	20
41119	70 mm ²	18,5 / 60	125 A	1 000 V / 150A	10




BORNES DE TERRE



RÉFÉRENCE	SECTION	L / H	EMBALLAGE
41190	1,5 mm ²	4,2 / 42,5	100
41191	2,5 mm ²	5,2 / 42,5	100
41192	4 mm ²	6,2 / 42,5	100
41193	6 mm ²	8,2 / 42,5	50
41194	10 mm ²	10,2 / 42,5	50
41195	16 mm ²	12,2 / 42,5	50
41196	35 mm ²	15,2 / 42,5	20




Bornes automatiques



RÉFÉRENCE	SECTION	L / H	INTENSITÉ	V / A	EMBALLAGE
41203	2,5 mm ²	5 / 53	20 A	800V / 24A	100
41204	4 mm ²	6 / 59	32 A	800V / 32 A	100
41205	6 mm ²	8 / 74,5	40 A	800V / 41A	50
41206	10 mm ²	10 / 78	50A	800V / 57A	25
41207	16 mm ²	12 / 94,5	63 A	800V / 76 A	25



BORNES DE TERRE



RÉFÉRENCE	SECTION	L / H	EMBALLAGE
41261	2,5 mm ²	5 / 53	100
41262	4 mm ²	6 / 59	100
41263	6 mm ²	8 / 74,5	50
41264	10 mm ²	10 / 78	50
41265	16 mm ²	12 / 94,5	50